element

FATIGUE AND FRACTURE TESTING

FOR THE RAIL INDUSTRY

CRACK PROPAGATION

FRACTURE

Once the combination of crack length and load reaches a critical point, a material will fracture. The purpose of the fracture toughness measurement is to estimate the relationship between failure stress and crack size and characterize the material's resistance to fracture under a specific set of circumstances. There are various methods for measuring this value, and the technique employed often depends on how the material behaves. For example, where the failure is expected to be brittle, a plane-strain fracture toughness measurement, KIC, may be made; where the failure mode is expected to be more ductile, the JIC or CTOD values may be more representative.

Plane-strain fracture toughness testing is unusual in that there can be no advanced assurance that a valid KIC will be determined in a particular test. Therefore compliance with the specified validity criteria of the specific method is essential. In particular, limits on the stress employed during fatigue pre-cracking or the ideal specimen size can only be calculated once the test result is known; consequently, estimates on the material performance must be made which can prove to be inaccurate.

Similar to a fatigue crack growth rate test, fracture toughness measurements are made on specimens with a pre-existing fatigue crack. They are prepared for a test in a similar way as crack propagation samples and for the same reasons.

The procedures for measuring toughness can vary in complexity. One of the simplest methods is plane-strain fracture toughness measurement conducted to ASTM E399. The measurement is made by deforming the test piece at a constant displacement rate. The crack opening displacement (COD) is recorded along with the load response. The test is continued until the sample has completely fractured. Once the sample has been broken open, the crack length is measured and the crack geometry assessed for compliance with the requirements.

The load vs. COD data is plotted, and a line of best-fit is drawn through the linear loading portion. A secant with a gradient of 95% of the best-fit (or other convenient reduction) is drawn. The point at which the secant intersects the test data gives the PQ value. The KQ is calculated from PQ and the initial crack length to give a preliminary fracture toughness result. This value is then qualified as the material property KIC if all of the validation criteria are met. If they cannot be met, the result is reported as a KQ value.

There are four main categories or validation criteria for ASTM E399:

- **S, ec e Ge e_.** - For the crack to be in a state of plane-strain, the geometry must conform to the requirements of the test standard.
- **C ac Ge e_.** - The fatigue crack must be between 45 and 55% of the sample width. The crack front must not exhibit excessive bowing.The fatigue crack must stay within the plane of the starter notch.
- **Fa_ g e P e c ac g C d_ s** - The choice of initial and final loads for the fatigue pre-crack is generally at the discretion of the test house, however, they must meet the validation criteria given by the standard. The crack length must lie in the envelope given by the test standard.
- **K Ca c a_** - The ratio of K_{Max}/KQ must be less than 1.10 to ensure the fracture is classified as brittle. The value of $2.5(KQ/\sigma_{YS})^2$ must be greater than the ligament length to ensure the fracture is linear-elastic. If one or more of these conditions is not met, a larger sample is recommended.

Other requirements may be stipulated within specific test standards or specifications; these are broadly highlighted as the most common points.

There are many commonly used internationally recognized test

Europe: +44 (0) 808 234 1667 Germany: +49 800 000 5137 Americas: +1 888 786 7555 Middle East: +971 800 353 6368
Contact.us@element.com - www.element.com